# ICO
SENSORS GUIDE

SENSOR CALIBRATION

To know when and how to calibrate:

Scan QR code

Or visit our YouTube channel

▶ / ondilo

1 CALIBRATION

Ondilo App

Remote control

2 CALIBRATION

Calibration pH probe

Calibration ORP probe

Choose the sensor to calibrate

Calibrate

Click on "calibrate"
Follow the instructions

3 CALIBRATION

Caution:

Calibrate in a dry and clean area at room temperature.

Dry your hands and your ICO before handling it.

Single use solutions.

4 CALIBRATION

Ondilo

ondilo.com

SENSOR REPLACEMENT

Video tutorial: How to replace a sensor?

Scan QR code   Or visit our YouTube channel

▶ **/ ondilo**

1 REPLACEMENT

Remove ICO from the water   Dry hands and ICO

2 REPLACEMENT

Remove sensor cap   Use sensor tool

To remove the sensor
To place the new sensor

3 REPLACEMENT


Place sensor cap back on ICO   Put ICO back in the water

**4** REPLACEMENT

Ondilo App   Remote control

5 REPLACEMENT

Calibration pH probe   Calibration ORP probe

Choose the sensor to reset

Reset (new sensor)

Click on "reset"
Follow the instructions

6 REPLACEMENT